Introductions for Splicing with UY2 Connector

- 1. Locate the joint by twisting the wires one full turn.
- 2. Clip wires evenly to 19mm (3/4") Minimum. (Do Not Strip Insulation.)
- 3. Hold Connector with button side down. Insert wires all the way into ports.
- 4. Self-stripping, insulated and moisture resistant connector for 2-wire solid Copper conductor combinations of 0.9-0.4 mm (19-26 AWG) having maximum insulation O.D. of 2.08mm (0.082 inches).



